



clear solutions Inc.

#9300, 9301 Slatwall Spinner Display Assembly Instructions


Tools Needed: Allen Wrench (Included)

2, Flip the assembled panels upside-down and place the turntable base on top as shown. Line up the pre-drilled holes in the base with the holes in the bottom of the panel assembly and fasten with the large hex screws provided.




1, Attach each side panel perpendicular to the one before - with the slatwall facing out. Use the large hex screws in the pre-drilled holes to join all 4 side panels together.


Large Hex Screws



Allen Wrench (1)



Large Hex Screws (14)



Screw Covers (14)

3, Tighten all Hex Screws and turn unit right-side-up. Finish the Tower Assembly by pressing the Button Caps into the Hex Screw Heads.

©Clear Solutions, Inc 8/28/2009